

TORQUE



Amp Clamp Sensor

Torque is measured by an amp clamp type sensor when the top drive motor is electric or hydraulic pressure sensor when the top drive is mechanical. The accuracy for electric torque is $\pm 0.5\%$ and $\pm 0.1\%$ for the mechanical torque.